

# L5-7 module production

[detector\\_map\\_2021\\_initial\\_with\\_notes\\_reorg.pdf](#) That is a pdf showing how everything was reorganized for the 2021 run

## L5-7

#	Stereo	Axial	Assembled	Surveyed	Mounted	Goodness of HMs (stereo/axial); notes	Mounted	Assignment
0 (proto)	0, hole on block							
0		19, hole on lever	10/31/14 (SU)	11/3/14 (SU)		bad channels in middle APVs		
1	5, hole on block	6, hole on lever	10/22/14 (SU)	10/28/14 (SU)		perfect	11/7/14 (SU)	B5
2	7, hole on block	8, hole on lever	10/22/14 (SU)	10/28/14 (SU)		perfect	11/7/14 (SU)	B6
3	9, hole on block	4	10/22/14 (SU)	10/29/14 (SU)		perfect	11/7/14 (SU)	B7
4	2, hole on block	3, hole on lever	10/27/14 (SU)	10/29/14 (SU)		perfect	11/7/14 (SU)	T5
5	10, hole on block	11, hole on lever	10/27/14 (SU)	10/29/14 (SU)		perfect	11/7/14 (SU)	T6
6			10/27/14 (SU)	10/29/14 (SU)		perfect	11/7/14 (SU)	T7
7	15, hole on lever	14, hole on lever	10/27/14 (SU)	11/3/14 (SU)		bad channels in APV furthest from beam/perfect		
8	1, hole on block	17, hole on lever	10/31/14 (SU)	11/3/14 (SU)		bad channels on both edges/bad channels in 2 APVs furthest from beam		
9	18, hole on block	13, hole on lever						
off								

"Golden" half-modules:

- 2
- 3
- 5
- 6 (overetched hybrid)
- 7 (Sylgard bubble)
- 8
- 9
- 10
- 11 (slot-side connector damaged but fixed)
- 12 (weird leakage current when partially wirebonded)
- 14 (wirebonds wrecked but repaired)
- 17
- 18

Stereo:

- 13 (hole 110, hole 214)

Axial:

- 15 (slot 52, 53)

Crappy: 0 (gimp), 16 (chipped APV, damaged connector), anything not golden (1 or 2 bad channels)

- 1 (slot 46, hole 17)
- 4 (slot 314)
- 19 (hole 365)