

- Cool down and take calibrations runs with old setup (?)
- Get it working with new OS and network
- Verify rate tests
- APV25 shaping time tuning
- Activate single event upset mon. and test
- Fix data format issue for status/config banks
- Improve GUIs
- Improve start/stop/reboot DAQ procedures
- Fix hvCaen
- APV overclocking
- APV emulation (header noise): follow up on CMS APV thread (code/firmware coming?)
- Analysis: finish data integrity analysis, F2H1 noise study, baseline occupancy shift