

2014 sensor production

Sensor #	Received	Tested	V _{dep} (V)	V _{break} (V)	Pinholes	Shorts	Opens	Glued to carbon fiber	Part of half-module	Notes
Sensor 152	7/13/11(AG)	(HPK)(UC SC)	120	600	-	-	-	3/11/14(TKN)	L4-L6 half-module 0	COMPLETE
Sensor 620	10/04/13(VF)	(HPK)(UC SC)	130	310	-	-	-	?	L4-L6 half-module ?	
Sensor 621	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	03/27/14(TKN)	L4-L6 half-module 1	COMPLETE
Sensor 622	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	03/27/14(TKN)	L4-L6 half-module 1	COMPLETE
Sensor 623	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	04/30/14 (TKN)	L4-L6 half-module 2	
Sensor 624	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	04/30/14 (TKN)	L4-L6 half-module 2	
Sensor 625	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	05/06/14 (TKN)	L4-L6 half-module 3	
Sensor 626	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	05/06/14 (TKN)	L4-L6 half-module 3	
Sensor 627	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	05/06/14 (PH)	L4-L6 half-module 4	
Sensor 629	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	05/06/14 (PH)	L4-L6 half-module 4	
Sensor 630	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	05/13/14 (TKN)	L4-L6 half-module 5	
Sensor 632	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module ?	Large surface scratch. Unclear if it's deep enough. Details to come.
Sensor 635	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	05/13/14 (TKN)	L4-L6 half-module 5	
Sensor 637	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	05/13/14 (PH)	L4-L6 half-module 6	
Sensor 638	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	05/13/14 (PH)	L4-L6 half-module 6	
Sensor 640	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module 7	
Sensor 642	10/04/13(VF)	(HPK)(UC SC)	130	880	-	-	-	?	L4-L6 half-module ?	
Sensor 643	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module 7	
Sensor 645	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module 8	
Sensor 646	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module 8	
Sensor 647	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module 9	
Sensor 648	10/04/13(VF)	(HPK)(UC SC)	130	580	-	-	-	3/11/14(TKN)	L4-L6 half-module 0	COMPLETE
Sensor 649	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module 9	
Sensor 650	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module ?	Observed long scratch near edge.
Sensor 652	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module 10	
Sensor 653	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module 10	
Sensor 654	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module ?	Observed large scuffed area near one end.
Sensor 655	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module 11	
Sensor 656	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module 11	
Sensor 657	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module 12	
Sensor 658	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module 12	
Sensor 661	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module ?	

Sensor 662	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module ?	
Sensor 663	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module ?	
Sensor 664	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module ?	
Sensor 665	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module ?	
Sensor 666	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module ?	
Sensor 668	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module ?	
Sensor 669	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module ?	
Sensor 670	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module ?	
Sensor 671	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module ?	
Sensor 672	10/04/13(VF)	(HPK)(UC SC)	130	>1000	-	-	-	?	L4-L6 half-module ?	
Sensor 1830	08/05/14 (OM/VF)	(HPK)(UC SC)		>1000	-	-	-	?	L4-L6 half-module ?	
Sensor 1831	08/05/14 (OM/VF)	(HPK)(UC SC)		990	-	-	-	?	L4-L6 half-module ?	
Sensor 1832	08/05/14 (OM/VF)	(HPK)(UC SC)		>1000	-	-	-	?	L4-L6 half-module ?	
Sensor 1834	08/05/14 (OM/VF)	(HPK)(UC SC)		>1000	-	-	-	?	L4-L6 half-module ?	
Sensor 1836	08/05/14 (OM/VF)	(HPK)(UC SC)		860	-	-	-	?	L4-L6 half-module ?	
Sensor 1837	08/05/14 (OM/VF)	(HPK)(UC SC)		860	-	-	-	?	L4-L6 half-module ?	
Sensor 1839	08/05/14 (OM/VF)	(HPK)(UC SC)		>1000	-	-	-	?	L4-L6 half-module ?	
Sensor 1840	08/05/14 (OM/VF)	(HPK)(UC SC)		>1000	-	-	-	?	L4-L6 half-module ?	
Sensor 1842	08/05/14 (OM/VF)	(HPK)(UC SC)		>1000	-	-	-	?	L4-L6 half-module ?	
Sensor 1843	08/05/14 (OM/VF)	(HPK)(UC SC)		900	-	-	-	?	L4-L6 half-module ?	

Sensor Channel Ordering

Sensor Drawing

