

GUN VAC interlock test

Initial reay 1 setting $2\text{e-}9$

faulted at $2.5\text{e-}10$ when vacuum was $4.1\text{e-}10$