

Offline Analysis 2019

Task List:

1. Raw ADC distributions
 - a. Occupancy induced baseline shifts
 - b. Dead channel lists
 - c. Database entries
2. Calibration Run and Hits on Tracks
 - a. Pulse parameterization
 - i. Investigate 3 parameter shape vs current 2 parameter shape
 - ii. Update hps-java and database
 - b. Calibration constants
 - i. Compare shape parameters extracted from both sources
 - ii. Database entries