

L0 Hybrid Production 2021

Hybrid #	Received	Passive Components Loaded / Cleaned	Sent to UCSC	HV Test	APV25s Loaded	Wirebonded	Tested	Results	Sent to SLAC	Bias Foil Attached	Part of Module	Location	Notes
1	05/19/2021 EP	05/03/2021 (CB)	2021-05-04 (by AS)	05/03 /2021 (CB)	2021-05-04 (by FMM)	2021-05-05 (by FMM)	2021-05-06 (by AS)	LOM01 Hybrid 2021	2021-05-06 (by AS)			Now in laser box on the left (marked accordingly)	
2	05/19/2021 EP	05/03/2021 (CB)	2021-05-04 (by AS)	05/03 /2021 (CB)	2021-05-04 (by FMM)	2021-05-05 (by FMM)	2021-05-06 (by AS)	LOM02 Hybrid 2021	2021-05-06 (AS)			Now in laser box on the right (marked accordingly)	
3	05/19/2021 EP	05/03/2021 (CB)	2021-05-04 (by AS)	05/03 /2021 (CB)	2021-05-04 (by FMM)	2021-05-05 (by FMM)	2021-05-06 (by AS)	LOM03 Hybrid 2021	2021-05-06 (by AS)			Now in new dry box on the right (marked accordingly)	
4	05/19/2021 EP	05/03/2021 (CB)	2021-05-04 (by AS)	05/03 /2021 (CB)	2021-05-04 (by FMM)	2021-05-05 (by FMM)	2021-05-06 (by AS)	LOM04 Hybrid 2021	2021-05-12 (by AS)			Now in new dry box on the left (marked accordingly)	
5	05/19/2021 EP	05/05/2021 (CB)	2021-05-06 (by AS /EP)	05/05 /2021 (CB)	2021-05-06 (by FMM)	2021-05-07 (by FMM)	2021-05-12 (by AS)	LOM05 Hybrid 2021	2021-05-12 (by AS)				
6	05/19/2021 EP	05/05/2021 (CB)	2021-05-06 (by AS /EP)	05/05 /2021 (CB)	2021-05-06 (by FMM)	2021-05-07 (by FMM)	2021-05-12 (by AS)	LOM06 Hybrid 2021	2021-05-12 (by AS)				
7	05/19/2021 EP	05/05/2021 (CB)	2021-05-06 (by AS /EP)	05/05 /2021 (CB)	2021-05-06 (by FMM)	2021-05-07 (by FMM)	2021-05-12 (by AS)	LOM07 Hybrid 2021	2021-05-12 (by AS)				
8	05/19/2021 EP	05/05/2021 (CB)	2021-05-06 (by AS /EP)	05/05 /2021 (CB)	2021-05-06 (by FMM)	2021-05-07 (by FMM)	2021-05-12 (by AS)	LOM08 Hybrid 2021	2021-05-12 (by AS)				
9	05/19/2021 EP	05/08/2021 (EP)	05/08 /2021 (AS /EP)	05/08 /2021 (EP)	2021-05-12 (FMM)	2021-05-13 (FMM)	2021-05-12 (by AS)	LOM09 Hybrid 2021	2021-05-12 (by AS)				
10	05/19/2021 EP	05/08/2021 (EP)	05/08 /2021 (AS /EP)	05/08 /2021 (EP)	2021-05-12 (FMM)	2021-05-13 (FMM)	2021-05-12 (by AS)	LOM10 Hybrid 2021	2021-05-12 (by AS)				
11	05/19/2021 EP	05/08/2021 (EP)	05/08 /2021 (AS /EP)	05/08 /2021 (EP)	2021-05-12 (FMM)	2021-05-13 (FMM)	2021-05-12 (by AS)	LOM11 Hybrid 2021	2021-05-12 (by AS)				
12	05/19/2021 EP	05/08/2021 (EP)	05/08 /2021 (AS /EP)	05/08 /2021 (EP)	2021-05-12 (FMM)	2021-05-13 (FMM)	2021-05-12 (by AS)	LOM12 Hybrid 2021	2021-05-12 (by AS)				
13	06/03 /2021 (CB)	05/14/2021 (EP)	2021-05-14 (AS)	05/14 /2021 (EP)	2021-05-17 (FMM)	2021-05-18 (FMM)	2021-05-12 (by AS)	LOM13 Hybrid 2021	2021-05-12 (by AS)				
14	06/03 /2021 (CB)	05/14/2021 (EP)	2021-05-14 (AS)	05/14 /2021 (EP)	2021-05-17 (FMM)	2021-05-18 (FMM)	2021-05-12 (by AS)	LOM14 Hybrid 2021	2021-05-12 (by AS)				
15	06/03 /2021 (CB)	05/14/2021 (EP)	2021-05-14 (AS)	05/14 /2021 (EP)	2021-05-17 (FMM)	2021-05-18 (FMM)	2021-05-12 (by AS)	LOM15 Hybrid 2021	2021-05-12 (by AS)				
16	06/03 /2021 (CB)	05/14/2021 (EP)	2021-05-14 (AS)	05/14 /2021 (EP)	2021-05-17 (FMM)	2021-05-18 (FMM)	2021-05-12 (by AS)	LOM16 Hybrid 2021	2021-05-12 (by AS)				
17	06/07/2021 (EP)	05/18/2021 (EP)	2021-05-19 (AS)	05/18 /2021 (EP)	2021-05-20 (FMM)	2021-05-20 (FMM)	2021-05-27 (by AS)	LOM17 Hybrid 2021	2021-06-04?? (by Cam?)			Bad APV. Left at UCSC. Fixed, now at SLAC.	
18	06/03 /2021 (CB)	05/18/2021 (EP)	2021-05-19 (AS)	05/18 /2021 (EP)	2021-05-20 (FMM) See Note	2021-05-20 (FMM)	2021-05-12 (by AS)	LOM18 Hybrid 2021	2021-05-12 (by AS)			2 chips cracked. Fixed, now at SLAC.	
19	06/07/2021 (EP)	05/18/2021 (EP)	2021-05-19 (AS)	05/18 /2021 (EP)	2021-05-20 (FMM)	2021-05-20 (FMM)	2021-05-27 (by AS)	LOM19 Hybrid 2021	2021-06-04?? (by Cam?)			Paired with LOM17, left at UCSC. Now at SLAC.	
20	06/08/2021 (EP)	05/19/2021 EP		05/19 /2021 EP	2021-05-24 (FMM)	2021-05-24 (FMM)	2021-05-27 (by AS)	LOM20 Hybrid 2021	2021-05-27 (by AS)				

[illegible]