

How to Recover SXR Undulator if Top Motors Lose Encoders (battery dies)

See here for detailed notes of what happens when the motor turns on after the battery is installed for the first time: [SXU motor encoder overflow issue](#)

This page also has information on how to open the undulator to max gap to reset the encoder offsets.